



Archerfield Airport Corporation

ABN 31 081 619 123
ACN 081 619 123

PO Box 747
Archerfield Qld 4108
Top floor Terminal building
Grenier Drive Archerfield Airport

p (07) 3275 8000
f (07) 3275 8001

12 August 2016

To: All Pilots, Operators and Tenants

Re.: Unsealed Runways 04L & 04R update

Archerfield Airport would like provide an update on the maintenance and repair works on its unsealed runways 04/22L and 04/22R.

Both runways showed considerable signs of scouring and rutting as well as poor drainage in certain sections, we therefore deemed operations of these runways unsafe.

We have now completed an aerial topography survey by drone to determine levels and ensure the grading design is correct. The drainage can then be altered so the water leaves the runway as soon as possible.

Notwithstanding the delays due recent wet weather conditions causing the runways to remain closed even longer we have now completed the works for RWY 04R and it is operational and open.

Repair and maintenance works on RWY 04L is scheduled to start in early September. It is our intent to re-open the runway as soon as it is serviceable, possibly 3 months after completing the works. (Subject to weather conditions and growth of the newly installed grassed surface and spray seeding)

We apologise for any inconvenience and would like to ask all tenants and operators to inform your staff and pilots about the repair and maintenance works of our unsealed runways.

If you have any queries please do not hesitate to contact our Operations & Technical Officer, Sebastian Seidel on 0414 233 903 or Sebastian@archerfieldairport.com.au

HEATHER MATTES
GENERAL MANAGER